


9348745

Ellice/R1.

① Fault Report

Customer Name: <i>ellice</i>	Date: <i>8/12/22</i>
Customer Reference: <i>348745</i>	Fitter: <i>CRACK M</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>SHUTTER KIT</i>	
Fault Description: <i>replace shutter panel in kit slats not turning properly video sent to graeme.</i>	
Action to correct: <i>Kit shutter panel</i>	
 <i>Right panel replace</i>	
Problem fixed on site: Yes/No	
Further action required: <i>Rework fit completed 17/04/23 CM</i>	

* 17/07/23 - Service call CM - need to speak to Graeme as the replacement panel is a different colour to the rest. - Photos sent to Graeme
Fault Report to follow.