

# Fault Report

Customer Name: <i>riverside school</i>	Date: <i>26/7/23</i>
Customer Reference: <i>350081</i>	Fitter: <i>CRAIG</i>
Salesperson: <i>Dave</i>	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: <i><del>est</del> remake headrail no (16) 1875mm remake vanes no (17) 1845mm (all measured) remake headrail no (1) 968mm wrong</i>	
Action to correct: <i>headrail no (16) at 1875mm vanes no (17) at 1845mm headrail no (1) 968mm</i>	
Problem fixed on site: Yes/No	
Further action required:	