

# Fault Report

Customer Name: Wilson	Date: 31.07.23
Customer Reference: 354966	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Vision blind and Velux blind (Kitchen)	
Fault Description: Vision blind has dirty fingerprints on from the fabrication Velux is creased due to blind not sitting straight on the roll. Photo's attached to email.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Remake vision send photos to Velux and ask them to replace it.	