

# Fault Report

Customer Name: <a href="#">Maughan</a>	Date: <a href="#">24.08.23</a>
Customer Reference: <a href="#">350288</a>	Fitter: <a href="#">Scott Johnson</a>
Salesperson: <a href="#">Dave</a>	Salesperson called: <a href="#">Yes</a>
Blind Type and number: <a href="#">Cassette Roller, Lounge bay 2</a>	
Fault Description: <a href="#">Measured incorrectly.</a>	
Action to correct: <a href="#">N/A</a>	
Problem fixed on site: <a href="#">No</a>	
Further action required: <a href="#">Cut down cassette to 2200mm recess size and roller to suit.</a>	