

TICKET G350257

CHAMPMAN

12 GLENEVILLE CLOSE
CHADLER PARK
NE 5159.

Customer Name: Date: 21/8/23
Customer Reference: Fitter:

Salesperson: Salesperson called: Yes/No DAVE

07935 125991

Blind Type and number: ROLLER X 1

RH FRONT BEDROOM

Fault Description:
HOLE IN B/OUT FABRIC.

2925 x 1170.

Action to correct:

ARRANGE FOR FITTER TO COLLECT AND SEND TO FACTORY, CUT
BOTTOM FABRIC OFF AND RE FIT BOTTOM BAR. CHECKED THAT
THERE IS EXCESS FABRIC ON ROLL.

Problem fixed on site: Yes/No

Further action required:

PLEASE COLLECT AS CLOSE TO VAN DRY AS POSSIBLE + RE FIT
AS SOON AS TO ALLOW MINIMUM IMPACT ON CUSTOMER.

Fault Report

CUSTOMER IS AWARE OF ALL THE ABOVE.

DAVE.