

G350469  
CALVERT /R/

# Fault Report

Customer Name: Calvert	Date: 11.10.23
Customer Reference: 350469	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Velux, Garage loft, Perfect fit, Bedroom	
Fault Description: Velux has a pin hole in the blackout material, please see images attached to email. Perfect fit pleated ordered incorrectly width and drop where ordered the wrong way round.	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Order new Velux GGL 606, Remake perfect fit correct way 762mm Width 854mm Drop.	