

G355164

HOGARTH / R.

# Fault Report

Customer Name: Hogarth	Date: 08.11.23
Customer Reference: 355164	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Rear bed, Roller	
Fault Description: Incorrect colour sent, Should be blackout white (WHITE) and blackout wine (RED) was sent	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Order new Blind or recover.	



# ROLLER BLINDS Order Form

Special Instructions  
CLOTH OFF THE FRONT

Date: 20110123  
Order Reference: 355104

Sales Rep: DAVE  
Customer Name: HOGARTH

Company / Shop:

BLIND SIZE & SYSTEM										CONTROLS					OPTIONS				
Location	Width (mm)	Drop (mm)	Recess (✓)	Exact (✓)	Child Safety Installation Height (mm)	System 3240/43/ Benthin	Fabric Range	Fabric Colour	Operation		Cassette Type & Colour	Roll	Finish	Bottom Bar	Bottom Bar End Caps				
									RHS (✓)	LHS (✓)									
1	1715	1045	✓		2050	32	Porous Blot	WHITE		✓	N/A	WHITE	1	NO	NON				
2																			
3																			
4																			
5																			
6																			
7																			
8																			

NOTE: UNLESS OTHERWISE STATED ALL MEASUREMENTS WILL BE TAKEN AS RECESS AND ALL OPTIONS WILL BE DEFAULT.

FITTING NOTES: