

Fault Report

Customer Name: Dobson	Date: 09.11.23
Customer Reference: 355181	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Office, Roller 1 (620 x 1350)	
Fault Description: Pin hole in then blackout material, see images	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Order new Blind.	