

Total Miles:

G 355316
BROWNLEE/R

Fault Report

Customer Name: Date: Brownlee 08-12-23.
Customer Reference: Fitter: Dan, 355316

Salesperson: Salesperson called: Yes No

Blind Type and number:
Vertical,

Fault Description:

Vertical track not working correctly
tracks not running. Track possibly bent.

Action to correct:

re make track.

Problem fixed on site: Yes No

Further action required:

re make vertical track a.s.a.p please.

