

G353323

DAWSON / R

Fault Report

Customer Name: Date: DAWSON 09.01.23.

Customer Reference: Fitter: DAN.

Salesperson: Salesperson called: Yes No

Blind Type and number: SHUTTER BED BAY NOS.

Fault Description:

FULL shutter SLAT SPINNING 360°

Action to correct:

Speak to graham for advice.

Problem fixed on site: Yes/No

Further action required:

Photo + video added to help solve problem.

