

ON 97142R

G 35304 SIDHU /
R.

Fault Report

Customer Name: Date: 353041 SIDHU.
Customer Reference: Fitter:

Salesperson: Salesperson called: Yes No

Blind Type and number: ROMAN BEG left

Fault Description:

BROKEN CHAIN.

Action to correct:

RE - ORDER CHAIN.

Problem fixed on site: Yes/No

Further action required:

PLEASE MAKE AND SEND CHAIN
@ 700MM CONTINUOUS.
