

356683

Fault Report

Customer Name: Date: Louise Wade.
Customer Reference: Fitter: 356683.

DAW

Salesperson: Salesperson called: Yes No

Blind Type and number:

Fault Description: **BAY 1.**

chunk missing in shutter.

Action to correct:

New Shutter bottom for bay 1.

Problem fixed on site: Yes No

Further action required:

chunk missing in bottom frame of shutter
customer caught me trying to repair. Not happy
and wants the bottom replaced.

of photos sent