

S356683

WADE

② Fault Report

Customer Name: WADE	Date: 20-6-24
Customer Reference: 356683.	Fitter: DAU.
Salesperson: DAVE	Salesperson called: Yes <input checked="" type="checkbox"/> No
Blind Type and number: SHUTTERS.	
Fault Description: Photos to show why shutter is fitted correctly its his window that is off as shown in video	
Action to correct: Spoke to gramem. No Action to correct	
Problem fixed on site: <input checked="" type="checkbox"/> Yes / No	
Further action required:	

Photo + Video added.

356683

① Fault Report

Customer Name: Date: Louise Wade.

Customer Reference: Fitter: 356683.

DAW

Salesperson: Salesperson called: Yes No

Blind Type and number:

Fault Description: BAY 1.

Chunk missing in shutter.

Action to correct:

New shutter bottom for bay 1.

Problem fixed on site: Yes No

Further action required:

chunk missing in bottom frame of shutter
customer caught me trying to repair. Not happy
and wants the bottom replaced.

* See fault report ②

of photos sent

