

G355455
BRUMBY / R

Fault Report



Customer Name: Brumby	Date: 15.02.23
Customer Reference: 355455	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller	
Fault Description: Fabric has marks, see images attached. First blind on order — Alvorotto	
Action to correct: tried to wipe it with a damp cloth.	
Problem fixed on site: No	
Further action required: Remake Blind and book a refit.	