

G355588

JOHNSTONE

Customer Date: 19/4/24
Name: JOHNSON
Customer Company:
Reference: 355588
Blind Type: FAUXWOODS

Alteration to be done: IN MY OPINION THERE IS NOTHING
REALLY WRONG WITH BLINDS AT ALL, MEASUREMENTS + FITTING
ALL GOOD BUT CUSTOMER BEING PARTICULARLY PICKY,

BLIND N° ② COULD BE 1/2" CLOSER TO CURTAIN R/4 SIDE +
PLINTH ON BLIND ② IF FITTED AS BELOW DIAGRAM WOULD
HIDE GAP A BIT BETTER,



PLINTH ② TO BE CUT SHORTER
WITH BLIND BRACKETS
BUTTING UP IN CORNERS.

Returned by:

Returns Report

Dan has gone back and
re-positioned blinds to
narrow down any gaps
and customer now happy.