

5356803  
MATTHEWS

## ③ Fault Report

<b>FITTER NAME:</b> Dan	<b>FITTING DATE:</b> 06-08-24
Customer Name: Matthews	
Customer Ref: 356803	
Salesperson: Shaun	Salesperson called: Yes/No Yes
Blind Type and number: All shutters upstairs	
Problem fixed on site: Yes/No    No	
Fault Description  Customer now complaining the shutters are fitted wrong and should be Z frames Photos taken.  All problems that this customer has had have been explained at time of measure	
Action to Correct:- Photos added to this report to show fitting of blinds	

Shaun to  
go back ref  
Z frames

No Answer from  
Customer