

# Fault Report

Customer Name: NICHOLSON	Date: 26/4/24
Customer Reference: Q355719 NICHOLSON	Fitter: —
Salesperson: DAVE	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number:	
Fault Description: FRONT BEDROOM LEFT SLAT DAMAGED	
Action to correct: REMOVE 3 SLATS + POST TO CUSTOMER.	
Problem fixed on site: Yes/No	
Further action required:	