

G351477

NASSAU/R

Fault Report

Customer Name: Date: Nassau
Customer Reference: Fitter: 351477
Salesperson: Salesperson called: Yes/No

Blind Type and number:

Fault Description: Shutters bay 2 x bed.

batters for side.

Action to correct:

Order battens.

Problem fixed on site: Yes/No
Further action required:

re order battens if made in this size,

R.U Bed 1 @ 90mm w x 1700 drop (5m)
2 @ 120~~mm~~w x 1700 drop. (5m)

LH Bed. 1 @ 90mm x 1700 drop (5m)
2 @ 110~~mm~~ x 1700 drop. (5m)

Real wood - Super white oak