

S356646

BISHOP AUCKLAND  
FAMILY HUB / R

# Fault Report

Customer Name:      Date: Orlene Anderson.

Customer Reference: Fitter: 356646

Salesperson:      Salesperson called: Yes  No

Blind Type and number:

Fault Description: roller door.

chain snapped.

Action to correct:

Need continuous chain

Problem fixed on site: Yes  No

Further action required:

Please send <sup>250mm</sup> ~~150mm~~ continuous chain and  
arrange to go and repair

& may be a idea to send a few  
lengths of different sizes of continuous  
chain to unit for me for jobs like this  
in future.

ON101224R