

S 356812

BAINBRIDGE

1R.

Fault Report

Customer Name: Date: Bainbridge 356812.
Customer Reference: Fitter: DAN

Salesperson: Salesperson called: Yes No Shawn.

Blind Type and number:

Fault Description: FBL - shutter frame.

Shutter damaged.

Action to correct:

Re order frame + kit box (hinge pins + screws ect).

Problem fixed on site: Yes No

Further action required:

Re order frame, ^{also hinge pins.} please contact customer next week just with update.

CUS aware of time will take. Very nice people and only guest b/room

- Photos taken and sent to gramen.

o Tried everything possible for temporary fix but not safe. customer happy to wait.