

ON 102 94321

② Fault Report

Customer Name: DOBSON	Date: 16-01-25
Customer Reference: 357410 SERVICECALL	Fitter: DAN
Salesperson: SHAUN	Salesperson called: Yes/No YLS
Blind Type and number: 1 x SHUTTER	
Fault Description:	
Action to correct: REMAKE LIV SIDE BAY - PAPERWORK ATTACHED	
Problem fixed on site: Yes /No	
Further action required: AS ABOVE	

Shutter Survey Sheet

Number of Shutters: 1	Survey Date: 16/01/25	Customer Name: DOBSON	Fitters Required: 1
Survey Sheets: 1	Surveyor: SHAWN H	Order Number: 357410	Estimated Fit Time:

Item Number	1	2	3	4	5
Room Name:	LIV SIDE				
Material:	BALMORAL WOOD				
Quantity:	1				
Width:	755				
Height:	1883				
Louvre Size:	76				
Colour:	CLASSIC IVORY				
Mounting Type:	FULL HEIGHT				
Mid Rail 1:	1150 CRITICAL				
Mid Rail 2:					
Louvre Split:					
Frame Type:	DEEP PLAN L60mm				
No. of Sides:	4				
Build Out:	LL				
Config:	AST				
Site Type:	LEARN				
Hardware:	HIDDEN				
Tilt Rod:					
Post Location 1:					
Post Location 2:					
Post Location 3:					
Post Location 4:					
Post Location 5:					
Post Angle 1:					
Post Angle 2:					
Post Angle 3:					
Post Angle 4:					
Post Angle 5:					

Panel Limitations (Single Panel / Bi Fold)	63mm	76mm	89mm	114mm
Balmoral Wood	850/650	850/650	850/650	850/650
Highgrove PVC	900/650	900/650	900/650	900/650
Balmoral Max Config	LLRR			
Highgrove PVC Max Config	LLRR			

Battens Required			Y / N
Batten Sizes (W X D)	Length	Quantity	

Order Information:

Balance to Pay:

Customer's Signature: _____

Date: _____

Surveyor Signature: _____

Date: _____

Baileys

34 HIGH STREET,
SPENNYMOOR,
DURHAM DL16 8DB

TEL: 01388 813267 or 0191 258 5956

sales@baileys-blinds.co.uk
www.baileys-blinds.co.uk

Customer's Name **DOBSON**

Address **10, WESTLANDS ROAD
EAGLESCLIFFE**

Post Code **TS16 0DZ**

Tel. home	
Tel. work	
mobile	07704 067923
email	

DATE MEASURED/ORDERED
11 / 09 / 24

Measured By:

SHAUN HANLEY

CURTAINS	
PLEATED	
ROLLERS	
ROMANS	
SHUTTERS	
VENETIAN	
VERTICALS	
VISION	
WOODEN	

SPECIAL INSTRUCTIONS

RND * 2 MAN FIT *
LIV SIDE (L) FIX
TRIM B/HIND SHUTTER
ON L SIDE TO COVER GAP
F/FIX BATH TO FRAME
*** FIT TOGETHER**

P/CUST	
NET	
PRESS	
RADIO	
MAG	
VAN	
RECC.	
SHOP	
TV	
YELL P	
OTHER	

Fitted By	DATE	DAY	AM	PM

alum	anthracite	black	brown	champ-gold	chrome	silver	white	recess size	motorised	wood fix	stone fix	brackets top	brackets face
									RECESSED	PVC	ROLL	✓	

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Price
BATH	763	1530	1/RW	ROLLER SPLASH SNOW SHAPE 1 STRAIGHT ROLL FROM FRONT	L	2600	108 86
FRONT BED	914	1819	76	SHUTTERS DEEP BULLNOSE 2 * FRAME 38mm - SILL PLATE * PEARL HINGES	M/A 1220	LR	581
LIV FRONT SIDE	2327	1888	76	DEEP PLAIN L60mm FRAME 4 SIDED	1150	LLRR	2051
TRIM	45 x 5 x 1828			CLASSIC IVORY BALMORAL WOOD 1 x 25 x 5 x 780 1 x 25 x 5 x 2327 x 1 1 x COGNAC POST 60 x 60 x 1580		LLRR DISC HIDDEN	2632 2105 45 2365

SAFETY DEVICES SUPPLIED WITH GOODS MUST BE FITTED BY US AT THE TIME OF INSTALLATION. IF YOU REFUSE TO ALLOW A SAFETY DEVICE TO BE FITTED, THEN THE GOODS WILL NOT BE INSTALLED, AND UNDER THESE CIRCUMSTANCES YOU WILL STILL BE LIABLE TO PAY THE FULL PRICE UNDER YOUR CONTRACT. YOU ARE STILL BOUND TO ACCEPT DELIVERY OF THE GOODS AND TO PAY FOR BOTH THE FITTING AND INSTALLATION EVEN ALTHOUGH INSTALLATION HAS NOT BEEN CARRIED OUT.

I have ordered the above goods and agree to pay 50% deposit and the remaining balance on the day of fitting. If payment is not made in full at that time Baileys Blinds has the right to remove the goods until full settlement is made. Title of the goods does not pass to the customer until payment has been made in full. Declaring that there shall be no liability for normal damage occasioned by such removal.

TOTAL PRICE	£ 2451
DEPOSIT	£ 1226
BALANCE	£ 1225

PRICE ACCEPTANCE Customer's Signature

*** DOBSON**

CASH	CHEQUE	CARD
		✓

ALL BLINDS TO BE PAID FOR AT TIME OF FITTING



① Fault Report

FITTER NAME: <u>Dan + Shaun</u>	FITTING DATE: <u>17-12-24</u>
Customer Name: <u>Dobson.</u>	
Customer Ref: <u>357410.</u>	
Salesperson: <u>Shaun</u>	Salesperson called: <input checked="" type="radio"/> Yes <input type="radio"/> No <u>Yes.</u>
Blind Type and number: <u>Shutter liv side.</u>	
Problem fixed on site: Yes <input type="radio"/> No <input checked="" type="radio"/>	
Fault Description <u>To big.</u> <u>⊗ must be 2 man to re fit</u>	
Action to Correct:- <u>Cut down 12mm each side</u> <u>and 6mm off drop.</u>	