

356812

# Fault Report

Customer Name: Date: Bainbridge 356812.

Customer Reference: Fitter: DAW

Salesperson: Salesperson called: Yes  No Shawn.

Blind Type and number:

Fault Description: FBL - shutter frame.

Shutter damaged.

Action to correct:

Re order frame + kit box (hinge pins + screws ect).

Problem fixed on site: Yes  No

Further action required:

also hinge pins.  
Re order frame, please contact customer  
next week just with update.

Cus aware of time will take. Very nice people  
and only guest b/room

Photos taken and sent to gramen.

Tried everything possible for temporary fix  
but not safe, customer happy to wait.

21/08/24 - service call for Magnets completed DA.

- Rework still to do - Rework order wrong. DA.