

FITTER NAME: FITTING DATE:

Customer Name: BURN

Customer Ref: 358207

Salesperson: Salesperson called: Yes/No

Blind Type and number: 2x ROLLERS.

ON/03004RZ

Problem fixed on site: Yes/No

Fault Description

GAPS IN BAY CORNER IS TOO BIG. CUSTOMER NOT HAPPY WITH GAPS, WON'T HAVE CLOTH OFF TAB FRONT. GOOD WILL SAYS TO REPLACE AS BELOW

Action to Correct:-

REPLACE BLIND ① WITH SMALLER ROLLER FITTED
IN AS CLOSE TO GLASS AS POSSIBLE.
1x BELLA FROST ROLLER 270 X 1310 LHM CONTROL. WHITE CHAIN
WITH NO SEN BOTTOM BAR, TOP FIX.

Fault Report