

Fault Report

FITTER NAME: GRAEME	FITTING DATE: 19-9-24
Customer Name: HENDERSON	
Customer Ref: 355829.	
Salesperson: DAVE	Salesperson called: <input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No
Blind Type and number: KITCHEN, BATHROOM + FRONT BED LEAT 1 NEEDS REMODE.	
Problem fixed on site: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Fault Description KITCHEN = 1117 x 961 CHANGE FRAME TO LARGE BULLNOSE. BATH = 541 x 962 CHANGE FRAME TO LARGE BULLNOSE. FRONT BED (1) 1693 x 1115 SAME SPEC AS BEHIND.	
Action to Correct:-	