

G358266
FLOW / R

Fault Report

ON103157R

FITTER NAME: DAN	FITTING DATE: 25/10/24
Customer Name: FLOW	
Customer Ref: 358266	
Salesperson: DAVE	Salesperson called: Yes/No
Blind Type and number: VELUX BLIND GGL104	
Problem fixed on site: Yes/ <u>No</u>	
Fault Description CORD ON LEFT SIDE OF THE BLIND ALL FRAYED AND HAS SNAPPED WHEN PULLED INTO POSITION	
Action to Correct:- ORDER NEW PLACE AND REPLACE. ALL OTHER BLINDS FITTED WITHOUT ANY ISSUES	

Baileys Blinds

A member of the G.C. Group

24 High Street
SPRINGTOWN
Co. Durham
DL16 6TB

Tel: 0191 201 6304 Fax: 0191 201 6305

Email: sales@baileysblinds.co.uk

TICKET 358266
Name FLOW
D.O.S. 30/9/24

To: Velux Blinds

Please supply the following Velux blinds :-

1x GGL 104 1025. WHITE BLIND ROLLER



2000
Ashington
Northampton

Tel: 01629 822643
Tel: 01225 202043

Gloucester
Leeds

Tel: 0191 201 6304
Tel: 0191 408 3185

Spangon
Sunderland

Tel: 01905 812267
Tel: 01463 611150

Website
www.baileys-blinds.co.uk