

Fault Report

FITTER NAME: DAN / SCOTT	FITTING DATE: 24-01-2025
Customer Name: BARDINI	
Customer Ref: 5357493 BARDINI (BAILEYS)	
Salesperson: SHAUN	Salesperson called: Yes/ <u>No</u>
Blind Type and number: SHUTTER LIVING ROOM FRONT	
Problem fixed on site: Yes/ <u>No</u>	
Fault Description LEFT PANEL + FRAME DAMAGED (CHIPPED / CRACKED)	
Action to Correct:- REMAKE REQUIRED .	