

G358340

MADDISON 12

Fault Report

FITTER NAME: Dan	FITTING DATE: 13.2.25.
Customer Name: Maddison.	
Customer Ref: 358340	
Salesperson: DAVE	Salesperson called: Yes (No)
Blind Type and number: Back Bed Shutter.	
Problem fixed on site: Yes (No)	
Fault Description Needs to pack left corner a few mm to bring middle down. Customer O.A.P and struggling to close. *Dan going back 19/2 to sort*	
Action to Correct:- Please re book appointment and allow time to remove shutter cut + re fit	

I have emailed Graeme to send down planer to take a bit of top to pack