

5357744
KAUROHESI /R

Fault Report

FITTER NAME: GRAEME	FITTING DATE: 19-12-24
Customer Name:	
Customer Ref: KAUROHESI	
Salesperson: SHAUN	Salesperson called: Yes <input checked="" type="checkbox"/> DONT ANSWER HIS PHONE!
Blind Type and number: MISSED 2 x WINDOWS IN THE PORCH.	
Problem fixed on site: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Fault Description 2 x BLINDS REQUIRED. RECESS SIZES. 1295 x 1565 LEFT CONTROL REVERSE ROLL 295 x 1565 RIGHT CONTROL REVERSE ROLL POLARIS B/O GREEN.	
Action to Correct:-	