

5356547
CROOKS / R.

ON/01064R

Fault Report

FITTER NAME: Dan.	FITTING DATE: 09.01.25.
Customer Name: Crooks.	
Customer Ref: 356547.	
Salesperson: Shaun.	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: INTU N° 1.	
Problem fixed on site: Yes/No	
Fault Description String in blind swapped, customer has tried to fix but made worse.	
Action to Correct:- re string blind and return.	