

G 3586+L
BELL/R1

② Fault Report

FITTER NAME: Dan	FITTING DATE: 04.03.25.
Customer Name: BELL.	
Customer Ref: 358672/R.	
Salesperson: Dave.	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Blind Type and number: Curved H/R.	
Problem fixed on site: Yes / <input checked="" type="radio"/> No	
Fault Description Re make as 1st blind the depth was wrong. now depth is fine but too long both sides sticking out past window. * only needs cut down @ bends if possible.	
Action to Correct:- Marked on blind where to cut & remove extra tracks. would try on site myself but don't know how to remove when on string.	