

C358554
BROWN /R.

Fault Report

FITTER NAME: Scott Johnson	FITTING DATE: 26.02.25
Customer Name: Brown	
Customer Ref: 358554	
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Shutters, Kitchen 1, Bathroom.	
Problem fixed on site: Yes/No	
<p>Fault Description: Some imperfections on shutters, see images in separate email. Kitchen 1 sill plate has chips in the paint along the cover strip edge, also has a chip and dent out if as well. Bathroom sill plate has a chip on it Bathroom right leg/side has discoloration on the bottom corner Bathroom Left door had a slight dent.</p>	
Action to Correct:- Order new sill plates for kitchen 1 and bathroom, order right leg for bathroom, Customer was going to speak to the wife about the door so either order new door or speak to customer to see outcome before ordering the Bathroom left door.	