

C1358672

BELL/RZ

③ Fault Report

ANI 04 046RZ

FITTER NAME: Dan	FITTING DATE: 25-03-25
Customer Name: BELL	
Customer Ref: 358672	
Salesperson: Dave	Salesperson called: Yes/No No
Blind Type and number: Curved track drapes	
Problem fixed on site: Yes/No No	
Fault Description 10 slats short for the curved track. Due to measuring issue at the start of The job	
Action to Correct:- Please send 10 slats need 46 only had 35 due to how it was measured originally	

Dave measure issue