

G358977
PURCELL/R

Fault Report

Customer Name: Purcell	Date: 19.05.25
Customer Reference: 358977	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Order Inputting Error	Mismeasure
Production Error	Supplier Error
Fitting Error	
Problem fixed on site: Yes/No	
Blind Type and number: Blind 4, Vertical, Con 4	
Fault Description: Headrail was made with a wand.	
Action to correct: Remake headrail with chain control as ordered. Right hand bunch right hand control.	