

5359183  
BARDINI / R

# Fault Report

Customer Name: Bardini	Date: 28-5-25.
Customer Reference: 359183.	Fitter: Dan.
Salesperson: Shaun.	Salesperson called: Yes/No (No).
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No (No)	
Blind Type and number: EN Suite shutter slats x6.	
Fault Description: Black scuffs + chips on both left + right shutter slats.	
Action to correct: re order slats x 6 and replace photos added for reference.	