

# Fault Report

FITTER NAME: Dan.	FITTING DATE: 08.07.25.
Customer Name: Caizley.	
Customer Ref: 358805.	
Salesperson: Dave	Salesperson called <input checked="" type="radio"/> Yes / No
Blind Type and number: Shutter back bed.	
Problem fixed on site: Yes/No	
Fault Description Shutter measured to tight to move for fitting / packers.	
Action to Correct:- Take 5mm from all 4 sides of shutter. LANDING / front Bed fitted.	

⊕ measuring fault