

55724

Fault Report

Customer Name: STOCKTON	Date: 30-07-25
Customer Reference: 357542	Fitter: DAN
Salesperson: SHAUN	Salesperson called: Yes/ No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes /No	
Blind Type and number: 1x PLEATED VELUX	
Fault Description: CUSTOMER NOT HAPPY WITH FABRIC ON BLIND - IS TRANSPARENT, HAVE AGREED TO SUPPLY NEW VELUX IN BLACKOUT FABRIC TO SOLVE PROBLEM * CUSTOMER HAS AGREED TO PAY £20 EXTRA ON FITTING OF NEW BLIND, THIS BEING THE DIFFERENCE BETWEEN STD & B'OUT FABRIC *	
Action to correct: SUPPLY 1x BLACKOUT PLEATED VELUX BLIND SIZE: GGL-4 (FHC) COLOUR FE86 TREND 1155	