

G 360871
GILBERT/R1

Fault Report

FITTER NAME: Scott	FITTING DATE: 21/8/25
Customer Name: Gilbert	
Customer Ref: 360871	
Salesperson: Dave	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Lounge Vertical	
Problem fixed on site: Yes/No	
Fault Description He has been made again with strings.	
Action to Correct:- Re-make with wood.	

G360871
Gilbert / B

Fault Report

Customer Name: Gilbert	Date: 30-07-25.
Customer Reference: 360871.	Fitter: Dan
Salesperson: Dave	Salesperson called: <input checked="" type="checkbox"/> Yes / No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes / <input checked="" type="checkbox"/> No	
Blind Type and number: living vertical.	
Fault Description: H/R on strings should be on wand.	
Action to correct: ✓ Make H/R with wand. wand on right blinds to go right to left * drapes with customer	

* all brackets fitted.

