

DN10S889K1

# Fault Report

FITTER NAME: L12	FITTING DATE: 3/1/10
Customer Name: RUTH LUMSDEN	
Customer Ref: 361129	
Salesperson: DAVE	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: 1 X SUNWOOD	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Fault Description PELMET DAMAGED.	
Action to Correct:- SUPPLIER TO SUPPLY PELMET.	