

Fault Report

Customer Name: Richardson	Date: 4/12
Customer Reference: 360006	Fitter:
Salesperson:	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: 6 X VELUX	
Fault Description: NO BRACKETS WITH BLINDS	
Action to correct: MORE BRACKETS ORDERED FROM VELUX AT CHARGE TO BAILEYS	