

S360195.
Bell 1h.

Fault Report

FITTER NAME: Dan	FITTING DATE: 07-01-2026
Customer Name: Bell	
Customer Ref: 360195 SERVICE CALL	
Salesperson: Shaun	Salesperson called: Yes/No No
Blind Type and number: 35mm hold down wood clips	
Problem fixed on site: Yes/No No	
Fault Description Customer unhappy with gaps in 50mm wooden bay window. Photos taken to show it's been fitted correctly and the brackets are all touching in the corners and Blind number 1 and 3 go to the wall so no way to make them bigger.	
Action to Correct:- Photos taken of bay window closed open and the brackets to show gapes. In my opinion there is nothing wrong but customer unhappy	