

S360271

Fault Report

Customer Name: CARR	Date: 04.03.26
Customer Reference: 360271	Fitter: DAN
Salesperson: SHAUN	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No	
Blind Type and number: 1x FAUXWOOD VEN	
Fault Description: GAP BETWEEN BOTTOM SLAT & BOTTOM RAIL WHEN BLIND CLOSED PICTURES ATTACHED	
Action to correct:	

07768584445 /