

G361641

②

Fault Report

FITTER NAME: Dan	FITTING DATE: 07-04-2026
Customer Name: Scullion/r	
Customer Ref: 361641	
Salesperson: Shaun	Salesperson called: Yes/No No
Blind Type and number: Pelmet number 4	
Problem fixed on site: Yes/No No	
Fault Description Pelmet requested from previous fault report to be pelmet number 4 to be cut With a right hand return also required would be a return piece and also the joining Clips. The suppliers have sent juts a straight edge piece of pelmet no returns cut and no Return and no joint clip.	
Action to Correct:- Please get suppliers to send new pelmet with the right hand side cut for a return Also return piece needed and joining clip Debbie has video / photo of the wrong one sent if suppliers need it	