

G 360880

# Fault Report

<b>FITTER NAME:</b> Dan	<b>FITTING DATE:</b> 20-04-26
<b>Customer Name:</b> Kennedy	/
<b>Customer Ref:</b> 360880	
<b>Salesperson:</b> Dave	<b>Salesperson called:</b> Yes/No No
<b>Blind Type and number:</b> Perfect fit number 2	
<b>Problem fixed on site:</b> Yes/No    No	
<b>Fault Description</b> Perfect for number 2 customer says fell out of the frame when all pulled up Together	
<b>Action to Correct:-</b> Unsure what to do until you have had a look at the photos for the damage. If Required I can call back to customer to collect and return to Bailys for a repair Photos added as where the damage has happened looks like it wasn't caused the Way the Customer is describing with it just falling out	