

G3601641

3

# Fault Report

<b>FITTER NAME:</b> Dan	<b>FITTING DATE:</b> 22-04-26
<b>Customer Name:</b> Scullion /	
<b>Customer Ref:</b> 361641/r	
<b>Salesperson:</b> Shaun	<b>Salesperson called:</b> Yes/No No
<b>Blind Type and number:</b> Pelmet number 4 and right hand return	
<b>Problem fixed on site:</b> Yes/No No	
<b>Fault Description</b> Pelmet sent again with no return cut	
<b>Action to Correct:-</b> Pelmet number 4 needs to be send with right hand return cut also need the Hand return small piece and a clip to attach. Check before booking job in as Last 2 times pelmet has been sent with no return cut  Photo added if suppliers want it	