



LEFT SIDE 1

LEFT SIDE 2



Rear



63mm
Sea Mist
50/50
CTW

Blinds and pelmets to be removed by cust
 Spur and trunking to be removed by customer
 Bottom trim on windows to be removed by us
 Not promised for Xmas