

L'HORIZON HOTEL

WEINOR PERGOTEX II ROOF SYSTEM SERVICING SHEET

Maintenance carried out by CP Interiors during quarterly service

DATE SERVICE CARRIED OUT: 12 May 2020

Service Sheet Signed: \_\_\_\_\_

Unit NO	1	2	3	4	5	6	7	8	9	10	11	12	13
1 Inspect installation for signs of wear and tear or damage to awning material and frame.	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2 Inspect installation for signs of wear and tear or damage to cables and leads.	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3 Cleaning of construction, side channels and gutters	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4 Greasing pulley blocks in front and wall support caps	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5 Checking the toothed belts tension force	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6 Checking the end position of the motor	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7 Checking the fabric for visible damage	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8 Checking fabric tension force	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9 Check remote controls operating correctly	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Comments	1x heater received Bilec HD 4x front end cap sets required (Suggest ordering 4 spares)												