**Staff Name** Adrian

# Work Diary

| Order No | Measurer or Fitter | Contact Address | Customer Ref | Date | Time |
|---|---|---|---|---|---|
| SO9867 | Measurer | Mrs.. Ferguson, La Petit Chateau, 3 Le Croix Crescent, La Rue a Don, Grouville, JE3 9DH, 840687, alan.ferguson2@gmail.com | | 20-04-2020 | 09:00 |

**Notes :** damaged terrazza , replace glass and remove existing glass ect ect

| Location | Supplier | Blind Type /Description | Colour | Qty | Width | Drop | Fitting Height | Blind/Recess | Controls | Brackets | Surface | Unit Price |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Remove | | | | | | | | | | |
| | | broken glass | | | | | | | | | | |
| | | and all seals to panel: | | | | | | | | | | |
| | | replace toughen glass and seals | | | | | | | | labour | | £ 720 |
| | | | | | | | | | | + | | |
| | | | | | | | | | | parts | | £ |
| | | | | | | | | | | | | £ 965-00 |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

| Comments: | Order Date | Customer Signature<br>X<br>I have checked and agree with the above choices |
|---|---|---|
| | | Target Fitting Date |