

Work Diary

Staff Name Adrian **Measurer or Fitter** Adrian **Contact Address** Mrs. J. Alfonso, La Tranquille, 3 Beauport Square, Plat Douet Road, St Savior, JE26PF, 07797 817590. **Customer Ref** P18 **Date** 22-07-2020 **Time** 12:00

Notes : Shutters measurement

Location	Supplier	Blind Type /Description	Colour	Qty	Width	Drop	Fitting Height	Blind/Recess	Controls	Brackets	Surface	Unit Price
Master		Plantation	TSA	1	1705	2040	OD+4 CURR					
Bed		Shutter 76					mid 1100					
		Silent tilt					3 sided L-76					
		"		1	1765	715	OD+4 CURR					
		"					3 sided L-76					
TV		"		1	Sill plate 4	2025	B. top side				Bulnope 2	
		"		1	1670	2025	OD+4 CURR				L-76	
		"					mid 1100					
Bed 2		"		1	1765	1165	OD+3 CURR					
Front		"									Bulnope 2	
Bed 3		"		1	2355	1175	OD+4 CURR				lower sill removed	
Back		"										
over stairs		"		1	2090	2055	OD+2 UR				mid 1100	
(latter needed)		"									4 side L-50	
LIV		"		1	1720	2020	OD+4 CURR				mid 1000	
BA		"									3 side L-76	
		"		1	640	1345	OD+1 L					
		"		1	1100	1345	OD+2 UR				FRANK	
		"		1	640	1345	OD+1 R				XPSA Patch on L-600 4 sided	

Comments: _____
 Order Date: _____
 Customer Signature: _____
 I have checked and agree with the above choices
 Target Fitting Date: _____