Order For Service/Repair

Supplier	**C P**
Order No.	**SO10579**
Customer Ref.	
Contact Tel.	**01534 768141**
Date of Order	**21-09-2020**
Date Required	**21-09-2020**

Invoice Details	
Name	Mr. Amory Charlesworth
Address	Les Genets Routes Des Gentes
	St Brelade
Postcode	JE38LF
Phone	07797 750225

Delivery Details	
Name	Mr. Amory Charlesworth
Address	Les Genets, Routes Des Gentes
	St Brelade
Postcode	JE38LF
Phone	07797 750225

Qty	Product Type	Fabric	Description	Location
1			Curtain frayed cord living room needs a repairing and measure bed room Bedroom blind bay window -FP Key will in the utility on worktop - they are out (teachers)	

Date	Issue & Action	Arrival Time	Departure Time	Fitter(s)	Hours Spent	Parts Required	Cost £
22/9	Collected 2x Curtain poles for repair	12.30	1.30	3R			£55
	~~Also measured Bay window~~						
	~~615 x 1535 L+C~~						
	~~1590 x 1535 Stan~~						
	~~615 x 1535 R+C~~						
8.10.20	Cord and 2 runners Replaced on BOTH TRACKS				2 hours		£90
						2 runners + cord	£12
	SD						
						Total:	

Repair + hang

AB + SD 4 Smins £90

work complete 26/10/20 NZ