




# SUB-CONTRACTORS JOB WORK REPORT

CLIENT NAME/SITE: REGUS	TASK ID 323PJ00092

DATE: <i>1/02/2021</i>	ARRIVAL TIME: <i>8:30</i>	DEPARTURE TIME: <i>09:30</i>
---------------------------	------------------------------	---------------------------------

TWO BLINDS THAT HAVE BEEN REPAIRED RETURN VISIT TO RE FITTED

ENGINEERS COMMENT:

CLIENT SIGNATURE: 	PRINT NAME: <i>Julietta Joaquim</i>
--	--